





Quick change screen printing system for in-line screen printing.

Insert the support frame into your machine once and leave it. Individual support plates all work off of the same zero point using a pin and bushing locating system Sturdy quick release clamps secure plate to frame for reliable and repeatable printing.

The rear vertical wall is movable and can be set at an infinite specific position to accommodate the distance of your conveyor width.

Support plates can range from very complex to a simple flat open area.







## **Stone Mountain Tool**

Ph:800-624-8665 or 770-929-016 Fax:770-929-0226 480 Gees Mill Business Court Conyers, GA 30013

Web: StoneMountainTool.com Contact Us at: S

Contact Us at: Service@stonemountaintool.com